



SEAT\p:\0275002\01\CAD\T1\027500201T1vm.DWG BES:SYF 03/29/04



0 1000 2000  
SCALE IN FEET  
CONTOUR INTERVAL 20 FEET





Reference: USGS 7.5' topographic quadrangle maps "Bellingham North, Wash.," revised 1994 and "Bellingham South, Wash.," revised 1995.

**GEOENGINEERS** 

**VICINITY MAP**

**FIGURE 1**






Notes: 1. The locations of all features shown are approximate.  
 2. This figure is for informational purposes only. It is intended to assist in the identification of features discussed in a related document. Data were compiled from sources as listed in this figure. The data sources do not guarantee these data are accurate or complete. There may have been updates to the data since the publication of this figure. This figure is a copy of a master document. The master hard copy is stored by GeoEngineers, Inc. and will serve as the official document of record.

References: Ronald T. Jepson and Associates, April 1990, April 2000. Ecology and Environment, May 1986.

**GEOENGINEERS**

**SITE PLAN  
(NORTHEASTERN PORTION)**

**FIGURE 3**



Notes: 1. The locations of all features shown are approximate.  
2. See GeoEngineers' report entitled "Interim Cleanup Action Plan," dated July 6, 2000 for details concerning the explorations shown on this figure.  
3. This figure is for informational purposes only. It is intended to assist in the identification of features discussed in a related document. Data were compiled from sources as listed in this figure. The data sources do not guarantee these data are accurate or complete. There may have been updates to the data since the publication of this figure. This figure is a copy of a master document. The master hard copy is stored by GeoEngineers, Inc. and will serve as the official document of record.

Reference: Base drawing produced from sketch provided by GeoEngineers' staff.



A-A' GEOLOGIC CROSS SECTION

FIGURE 4